Weathertzation Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0816/1

Work Order Type: Weatherization

Audit Name: 17017UC-0816

CLIENT INFORMATION

Client ID: 17017UC-0816

AGENCY INFORMATION

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Fax:

Address: 3313 Williams Enterprise Drive

Cookeville, TN 38506 Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Mobile home built 1972

Measures

Ме	easure 1 Ce	iling Repairs 80 sq. ft			Componen	its		ı	Inspected
Coi	mment 80 sq.	ft.							
	·				Estimated	1		Actual	
# M	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 U	Inspecified	Sheetrock / 32sqft	Each	80					
Oth	ner Detail								
				Measur	e Sub Total:			Sub Total:	
Fi	ield Notes:								
Me	easure 2 Sill	Replacements 6 ft			Componen	nts			Inspected
	easure 2 Sill	Replacements 6 ft			Componen	nts			Inspected
		Replacements 6 ft			Component Estimated			Actual	Inspected
Coi		Replacements 6 ft Description / Comment	Units	Qty	-		Qty		Inspected Total
Cor # M	mment		<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Col # M 10 U	mment Naterial / Labor	Description / Comment Replace Sills around		_	Estimated	<u> </u>	Qty	Actual	
Coi # M 10 U	mment Material / Labor Unspecified	Description / Comment Replace Sills around		_	Estimated	<u> </u>	Qty	Actual	
Coi # M 10 U	mment Material / Labor Unspecified	Description / Comment Replace Sills around		_	Estimated	<u> </u>	Qty	Actual	
Col # M 10 U	mment Material / Labor Unspecified	Description / Comment Replace Sills around	Each	1	Estimated	<u> </u>		Actual	
# M 10 U	mment flaterial / Labor Unspecified ner Detail	Description / Comment Replace Sills around	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# M 10 U	mment Material / Labor Unspecified	Description / Comment Replace Sills around	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# M 10 U	mment flaterial / Labor Unspecified ner Detail	Description / Comment Replace Sills around	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

		n Replacement 160 ft. o help seal leaky home			Componen	ts			Inspected
		p			Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Replace or Repair Trim around Windows	Each	1					
0	ther Detail								
L									
				Measur	e Sub Total:]	Sub Total:	
	Field Notes:								
	Measure 4 Sea	l Ducts			Componen	ts			Inspected
	omment Ducts: r Seal rep	I Ducts eplace insulate ducts, 30 pair ducts with mastic x 9 aulk inside return air vent		seal wa	ll cavity)				Inspected
C	omment Ducts: r Seal rep seal / ca	eplace insulate ducts, 30 pair ducts with mastic x 9 aulk inside return air vent	(include s		ll cavity) Estimated	,	Ofv	Actual	
<i>C</i>	omment Ducts: r Seal rep	eplace insulate ducts, 30 pair ducts with mastic x 9		eal wa	ll cavity)		Qty		Total
#	omment Ducts: r Seal rep seal / ca	eplace insulate ducts, 30 pair ducts with mastic x 9 aulk inside return air vent Description / Comment	(include s	Qty	ll cavity) Estimated	,	Qty	Actual	
# 1	omment Ducts: r Seal rep seal / ca Material / Labor Insulation Miscellaneous	eplace insulate ducts, 30 pair ducts with mastic x 9 aulk inside return air vent **Description / Comment** Duct sealing (setup cost)	(include s <i>Units</i> Each	Qty 1	ll cavity) Estimated	,	Qty	Actual	
# 1	omment Ducts: r Seal rep seal / ca Material / Labor Insulation Miscellaneous Supplies	eplace insulate ducts, 30 pair ducts with mastic x 9 aulk inside return air vent **Description / Comment** Duct sealing (setup cost)	(include s <i>Units</i> Each	Qty 1	ll cavity) Estimated	,	Qty	Actual	
# 1	omment Ducts: r Seal rep seal / ca Material / Labor Insulation Miscellaneous Supplies	eplace insulate ducts, 30 pair ducts with mastic x 9 aulk inside return air vent **Description / Comment** Duct sealing (setup cost)	(include s <i>Units</i> Each	Qty 1	ll cavity) Estimated	,	Qty	Actual	
# 1	omment Ducts: r Seal rep seal / ca Material / Labor Insulation Miscellaneous Supplies	eplace insulate ducts, 30 pair ducts with mastic x 9 aulk inside return air vent **Description / Comment** Duct sealing (setup cost)	(include s <i>Units</i> Each Each	Qty 1 1	ll cavity) Estimated	,		Actual	
# 1 10 C	omment Ducts: r Seal rep seal / ca Material / Labor Insulation Miscellaneous Supplies	eplace insulate ducts, 30 pair ducts with mastic x 9 aulk inside return air vent **Description / Comment** Duct sealing (setup cost)	(include s <i>Units</i> Each Each	Qty 1 1	Il cavity) Estimated Unit Cost	,		Actual Unit Cost	
# 1 10 C	omment Ducts: r Seal rep seal / ca Material / Labor Insulation Miscellaneous Supplies Other Detail	eplace insulate ducts, 30 pair ducts with mastic x 9 aulk inside return air vent **Description / Comment** Duct sealing (setup cost)	(include s <i>Units</i> Each Each	Qty 1 1	Il cavity) Estimated Unit Cost	,		Actual Unit Cost	

Measure 5 General Air Sealing			Components					Inspecte	
Comment caulk le caulk 8	60 linear foot foot door frame and casii	ng							
			Estimated				Actual		
# Material / Labor	terial / Labor Description / Comment		Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	General air sealing (setup cost)	Each	1						
Miscellaneous Supplies	Infiltration Reduction	Each	1						
Other Detail									
						1			
Field Notes:			Measur	e Sub Total:		,	Sub Total:		
Measure 6 Roo	of Cellulose Loose q ft. R-19 insulation		Measur	e Sub Total:	ts		L	Inspecte	
Measure 6 Roo			Measur				L	Inspecte	
Measure 6 Roc Comment 1470 se		Units	Measur Qty	Componen		Qty	L	Inspecte	
Measure 6 Roo Comment 1470 se # Material / Labor	q ft. R-19 insulation			Componen Estimated			Actual		
Measure 6 Roo Comment 1470 se # Material / Labor	q ft. R-19 insulation Description / Comment Roof Insulation -	Units	Qty	Componen Estimated			Actual		
Measure 6 Roo Comment 1470 so # Material / Labor 3 Other	q ft. R-19 insulation Description / Comment Roof Insulation -	Units	Qty	Componen Estimated			Actual		
Measure 6 Roo Comment 1470 so # Material / Labor 3 Other	q ft. R-19 insulation Description / Comment Roof Insulation -	Units	Qty	Componen Estimated			Actual		
Measure 6 Roo Comment 1470 so # Material / Labor 3 Other	q ft. R-19 insulation Description / Comment Roof Insulation -	Units Each	Qty 1	Componen Estimated		Qty	Actual		

Measure 7 Belly	/ Cellulose Loose			Componen	ts			Inspected
Comment **{{NEEI	OS 1470 sq. ft. Mobile ho	me undei	belly r	epair & r-11	fiberglas	s}}**		
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Celluls,Blwn	Bag	61					
2 Labor	Floor Insulation - Celluls,Blwn	Bag	61					
3 Other	Floor Insulation - Celluls,Blwn	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 8 Smo	ke Detector is Needed			Componen	ts			Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	9-volt Smoke Detector	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:				L				